POWER STEERING SYSTEM

510CT–01

PRECAUTION

1. HANDLING PRECAUTIONS OF STEERING SYSTEM

(a) Care must be taken when replacing parts. Incorrect replacement could affect the performance of the steering system and result in hazard to the driving condition.