LIGHTING SYSTEM

650ED–03

PRECAUTION

1. PRECAUTION FOR HEADLAMP BULB REPLACEMENT

(a) If there is oil on a halogen lamp (headlamp) surface, the lamp will become hotter when turned on, thus shortening the lamp service life.

(b) Since a halogen lamp bulb (headlamp) contains high pressure gas, carefully handle the lamp. Dropping a bulb may cause an explosion and scatter pieces in all directions.

(c) If a bulb has been removed from the lens for a long time, there may be dirt or moisture on the lens. So, remove the bulb after preparing a new one.

(d) Always use a bulb having the same watt rating.

(e) Firmly reinstall the socket cover after bulb replacement. Otherwise, water will penetrate and the lens will be clouded.