730A6–02

PROBLEM SYMPTOMS TABLE

Symptom	Suspected Area	See Page
Door lock control system does not operate.	1. POWER WINDOW fuse	–
	2. Door lock assy (Door lock control switch) (Driver side)	73–5
	3. Integration relay	73–3
	4. Door lock actuator	73–5
	5. Wire harness	–