# FRONT CROSSMEMBER (ASSY)




F25274A

Symbol meaning

| | |
|---|---|
| REMOVAL | : Remove Weld Points |
| INSTALLATION | : Spot Weld : MIG Plug Weld |

F25274B

**REMOVAL·INSTALLATION**




F25274

**INSTALLATION POINT**

1 Inspect the fitting of the related parts around the new parts before welding. This affects the appearance of the finish.
2 Temporarily install the new parts and measure each part of the new parts in accordance with the body dimension diagram. (See the body dimension diagram)
3 After welding, apply body sealer to the corresponding parts. (See the paint·coating)