COWL TOP TO APRON BRACE (ASSY)



F25277A


Symbol meaning

REMOVAL	: Remove Weld Points	: Cut with disc sander, etc.
INSTALLATION	: MIG Plug Weld	: Tack Weld


F25277B

REMOVAL·INSTALLATION

[LH]



[RH]



mm (in.)

F25277

INSTALLATION POINT

1 After welding, apply body sealer to the corresponding parts. (See the paint·coating)
2 After applying the top coat, apply anti-rust agent to the internal panel portion of the closed section structural weld points.