F RELAY LOCATIONS

: Center J/B	LHD : Instrument Panel Reinforcement LH (See Page 21)
	RHD : Instrument Panel Reinforcement RH (See Page 21)

