INTRODUCTION

OUTLINE OF NEW FEATURES


The following changes have been made for the new HIACE.

1. Lighting

Each room light on the vehicle rear has been changed on the Morocco package commuters. For details, see page 9.

2. Glass Roof Window for Emergency Escapes

- An emergency hammer (back window glass hammer assembly) for the tilt roof glass sub-assembly (for emergency escapes) has been provided at the roof of the Morocco package commuters.
- For Morocco package commuters, the installation position of the emergency hammer (back window glass hammer assembly) for the front side window assembly LH (for emergency escapes) which is installed in the roof side has been changed to vehicle front.



04Z9MO01D