INTRODUCTION

OUTLINE OF NEW FEATURES

The following changes have been made for the new HIACE.

1. Model Line-up


The discontinued models are shown in the table below.

Destination	Discontinued Model Code
Australia	TRH223R-LEMDKQ
General Countries	KDH223R-LDPNY

2. Exterior

- Color bumper* for front bumper cover and rear bumper cover has been provided as optional equipment of DX grade except models for Malaysia and part of models for South Africa.
- Dark plating for upper radiator grille and lower radiator grille has been adopted for part of models for Hong Kong package.


*: Color bumper does not allow to be selected when the exterior color No. 599 (light yellow) is selected.



26T3MO02

3. Interior

For some Hong Kong package models, position indicator housing assembly color has been changed to dark silver from silver.



26T3MO01

4. Engine

- Specifications for 1KD-FTV engine for Australia and New Zealand models have been modified for compliance with EURO V regulations from EURO IV regulations.
- Specifications for 2KD-FTV engine for Vietnam models that complied with EURO II regulations have been changed to 1KD-FTV engine that comply with EURO IV regulations.
- Specifications for 2TR-FE engine for Vietnam models have been modified for compliance with EURO IV regulations from EURO II regulations.

5. Seat

A Child Restraint System (CRS) has been adopted for part of the models for New Zealand package models.

6. Lighting

- A No. 2 room light assembly (at roof center and roof rear) and No. 2 room light assembly (at rear door scuff plate) of switch less type has been adopted for part of the China package models, and No. 1 room light switch assembly has been added on the instrument panel. Each room light* on the vehicle rear has been able to turn on/off only with the No. 1 room light switch assembly.
- A No. 2 room light assembly (at roof center and roof rear) less specification has been adopted for part of the China package models.


*: No. 2 room light assembly (at roof center and roof rear) and No. 2 room light assembly (at rear door scuff plate).

7. Door Lock Control System

Front door lock cylinder assembly on the front passenger seat side door has been abolished in some models except for G.C.C. countries and South Africa.

8. No. 2 Power Outlet Socket Assembly

The cigarette lighter assembly of the models except for G.C.C. countries and South Africa has been abolished and the No. 2 power outlet socket assembly has been adopted.



26T3BE01D

9. Under Mirror


Side under mirror (outer under view mirror assembly) and rear under mirror (outer under rear view mirror assembly) have been adopted for the models for Bangladesh that is part of the models for general countries.

10. Fuel Tank Cap Assembly

A key type fuel tank cap assembly has been provided to the super long wheel base models for Vietnam.

11. Escape Hammer and Label

- Hammers (4 in total) with buzzer have been adopted for part of the China package models.
- A pictogram mark has been added on the hammer attack point labels.
- Back window glass hammer assembly and label have been applied on the following location.



: Installation Position of Back Window Glass Hammer Assembly
: Operation Explanation Label Attachment Position
: Hammer Attack Point Label Attachment Position

26T3BO01