COMBINATION METER

HOW TO PROCEED WITH TROUBLESHOOTING

05JT5–01

1	VEHICLE BROUGHT TO WORKSHOP

2	CUSTOMER PROBLEM ANALYSIS (SEE PAGE 05–957)

3	PROBLEM SYMPTOM CONFIRMATION (SEE PAGE 05–970)

4	CHECK MULTIPLEX COMMUNICATION SYSTEM (SEE PAGE 05–1132)

(a) Check for DTC outputs.

	MULTIPLEX DTC OUTPUTS (PROCEED TO "BODY MULTIPLEX COMMUNICATION SYSTEM")
	NO MULTIPLEX DTC (GO TO STEP 5)

5	CHECK CAN COMMUNICATION SYSTEM (SEE PAGE 05–1179)

(a) Check for DTC outputs.

	CAN DTC OUTPUTS (PROCEED TO "CAN COMMUNICATION SYSTEM")
	NO CAN DTC (GO TO STEP 6)

6	CIRCUIT INSPECTION (SEE PAGE 05–971 – 05–984)

7	REPAIR OR REPLACE

8	CONFIRMATION TEST

END