

QUARTER LOCK PILLAR REINFORCEMENT (CUT)


F21030-A


REPLACEMENT
With the quarter panel removed.

REMOVAL



F23978

30 mm (1.18 in.)



POINT

1 Inspect the fitting of the quarter window glass and back window glass, etc., before welding, since this affects the appearance of the finish.