

F ELECTRICAL WIRING DIAGRAM (System Circuits)




3
4
* 1 : 2RZ-FE
* 2 : 1RZ, 3RZ-F
* 3 : w/ Daytime Running Light
* 4 : Cold Area Spec.
* 5 : Except Cold Area Spec.
W-R
W
R
B-R
5 1H
6 1H
10A GAUGE
10A IGN
1 1J
1 1D
B-W
JUNCTION CONNECTOR
J 9 B, J12 A
A (*1)
B (*2)
CHARGE WARNING LIGHT [COMB. METER]
C 9 A, C10 B
9 A
1 B
To Daytime Running Light Relay<203-3>
To Carburetor <194-2>
Y-B
(*3)
(*2)
D B
E A
J 3 A, J 4 B
JUNCTION CONNECTOR
JUNCTION CONNECTOR
J 1 A, J 2 B
C A
1 EB1
3 EB1
4 EB1
3 A
S
B B
IG A
L A
1
2
1
W
W-R
R-L
Y-B
A10 A, A11 B
ALTERNATOR