PP3XM–01

EQUIPMENT

Torque wrench	
Dial indicator with magnetic base	Drive plate runout
Vernier calipers	Torque converter
Straight edge	Torque converter