ABS & HYDRAULIC BRAKE BOOSTER POWER SUPPLY SYSTEM

HOW TO PROCEED WITH TROUBLESHOOTING

DIC3T–01

Troubleshoot in accordance with the procedure on the following pages.



★: Refer to LAND CRUISER Repair Manual Pub. No. RM616E

Step 2, 5, 8, 9, 11: Diagnostic steps permitting the use of the hand–held tester.