TOYOTA Service Bulletin

Section : Body

Ref. No. : B–4022

Date : Jul., 2004

Area Application : Europe, General, G.C.C. Countries, Australia

Model Name : LAND CRUISER PRADO

Model Code : TRJ120, TRJ125, GRJ120, GRJ125, LJ120, LJ125, KZJ120

Subject : Supplement for Body Repair Manual

This Service Bulletin is to inform you of body repair procedure.

The attached pages are to be used with the following manual.

Pub. No.	Publication Name
BRM114E	LAND CRUISER PRADO Repair Manual for Collision Damage

Production Effective :

VIN	Production Date
–	From August, 2004