STARTING & CHARGING

022GF–01

PREPARATION

Equipment

Ammeter (A)	
Ohmmeter	
Service Wire Harness	
Slide calipers	
Torque wrench	