STARTING & CHARGING

024BW–01

PREPARATION

Equipment

Ammeter (A)	
Ohmmeter	
Torque wrench	