
MAP DISC READ ERROR

INSPECTION PROCEDURE

1	CHECK MAP DISC



(a) Check for dirt on the map disc surface.
OK: No dirt is on the map disc surface.


HINT:
If dirt is on the map disc surface, wipe it clean with a soft cloth from the inside to the outside in a radial direction.

NOTICE:
Do not use a conventional record cleaner or anti–static preservative.

NG → **CLEAN MAP DISC**

OK

2	CHECK MAP DISC



(a) Check that the map disc is not deformed or cracked.
OK: No deformations or cracks appear on the map disc.

NG → **REPLACE MAP DISC**

OK

PROCEED TO NEXT CIRCUIT INSPECTION SHOWN IN DIAGNOSTIC TROUBLE CODE CHART
(SEE PAGE 05–1322)