510K4–01

# PROBLEM SYMPTOMS TABLE

HINT:

Use the table below to help find the cause of the problem. The numbers indicate the priority of the likely cause of the problem. Check each part in order. Repair or replace parts as necessary.

| Symptom | Suspected Area | See page |
|---|---|---|
| Hard steering | 1. Tires (Improperly inflated) | ★ |
| | 2. Power steering fluid level (Low) | ★ |
| | 3. Drive belt (Loose) | ★ |
| | 4. Front wheel alignment (Incorrect) | ★ |
| | 5. Steering system joints (Worn) | – |
| | 6. Suspension arm ball joints (Worn) | ★ |
| | | ★ |
| | 7. Steering column (Binding) | – |
| | 8. Power steering vane pump (2TR–FE Engine) | 51–9 |
| | 9. Power steering link assy | ★ |
| Poor return | 1. Tires (Improperly inflated) | ★ |
| | 2. Front wheel alignment (Incorrect) | ★ |
| | 3. Steering column (Binding) | – |
| | 4. Power steering link assy | ★ |
| Excessive play | 1. Steering system joints (Worn) | – |
| | 2. Suspension arm ball joints (Worn) | ★ |
| | | ★ |
| | 3. Intermediate shaft, Sliding yoke (Worn) | – |
| | 4. Front wheel bearing (Worn) | ★ |
| | 5. Power steering link assy | ★ |
| Abnormal noise | 1. Power steering fluid level (Low) | 51–3 |
| | 2. Steering system joints (Worn) | – |
| | 3. Power steering vane pump (2TR–FE Engine) | 51–9 |
| | 4. Power steering link assy | ★ |

HINT:

★: Refer to repair manual RM990E