SOUND QUALITY IS BAD ONLY WHEN CD IS PLAYED (VOLUME IS TOO LOW)

INSPECTION PROCEDURE

1	REPLACE CD WITH ANOTHER AND RECHECK

(a) Replace the CD with another and recheck.
  (1) Check the installation condition of the radio receiver assembly.
  Standard: malfunction disappear.

OK → **CD FAULTY**

NG

CHECK AND REPLACE RADIO RECEIVER ASSY