COMBINATION METER

HOW TO PROCEED WITH TROUBLESHOOTING

056Q7–02

1	Vehicle Brought to Workshop

2	Customer Problem Analysis (See page 05–1547)

3	Problem Symptom Confirmation (See page 05–1559)

4	Circuit Inspection (See page 05–1560 – 05–1586)

5	Repair or Replace

6	Confirmation Test

7	End