05AF2–01

PROBLEM SYMPTOMS TABLE

Symptom	Suspected Area	See Page
Key reminder buzzer does not sound	1. Un–lock warning switch assy	05–1726
	2. Front door courtesy lamp switch (Driver side)	05–1726
	3. Instrument panel junction block assy (Body ECU)	05–1723
	4. Combination meter	–
	5. Wire harness	–