THEFT DETERRENT SYSTEM

HOW TO PROCEED WITH TROUBLESHOOTING

05ABB–01

HINT:

Troubleshoot in accordance with the procedures on the following pages.

1	VEHICLE BROUGHT TO WORKSHOP

2	CUSTOMER PROBLEM ANALYSIS CHECK AND SYMPTOM CHECK (See page 05–1791)

3	INSPECT COMMUNICATION FUNCTION OF LARGE–SCALE MULTIPLEX COMMUNICATION SYSTEM (BEAN)

(a) Check that there is no abnormality in the communication system by inspecting the communication function of the multiplex communication system with the hand–held tester.

(1) (ECU unconnected, communication line abnormal) Without code outputs, proceed to A.

(2) (ECU unconnected, communication line abnormal) With code outputs, proceed to B.

B	Go to MULTIPLEX COMMUNICATION SECTION (See page 05–1822)

A

4	PROBLEM SYMPTOMS TABLE (See page 05–1792)

(a) Without applicable symptoms, proceed to A.

(b) With applicable symptoms, proceed to B.

B	Go to step 6

A

5	ACCORDING TO PROBLEM SYMPTOM, PERFORM TROUBLESHOOTING

(a) Terminals of ECU (See page 05–1794)

(b) On–vehicle inspection (See page 73–34)

6	ADJUST, REPAIR OR REPLACE

END