

4. COMPONENTS

(a) FRONT BUMPER






CAUTION:

The bolts and nuts must be tightened to the torque specification, as they are related to vehicle safety during a collision.


N·m (kgf·cm, ft.·lbf) : Specified torque

F30954

(b) REAR BUMPER




(c) INSTRUMENT PANEL



CAUTION:
The bolts and nuts must be tightened to the torque specification, as they are related to vehicle safety during a collision.

N·m (kgf·cm, ft.·lbf) : Specified torque


F30957



CAUTION:
The bolts and nuts must be tightened to the torque specification, as they are related to vehicle safety during a collision.

N·m (kgf·cm, ft.·lbf)	: Specified torque

F30958





CAUTION:
The bolts and nuts must be tightened to the torque specification, as they are related to vehicle safety during a collision.


N·m (kgf·cm, ft.·lbf) : Specified torque

F30959

(d) INTERIOR TRIM




REAR DOOR SCUFF PLATE OUTSIDE RH
FRONT DOOR SCUFF PLATE OUTSIDE RH
REAR FLOOR MAT REAR SUPPORT PLATE
REAR STEP COVER
REAR STEP COVER
REAR DOOR SCUFF PLATE RH
FRONT DOOR SCUFF PLATE RH
FRONT DOOR SCUFF PLATE LH
REAR DOOR SCUFF PLATE LH
FRONT DOOR SCUFF PLATE OUTSIDE LH
REAR DOOR SCUFF PLATE OUTSIDE LH
F30961




CAUTION:

The bolts and nuts must be tightened to the torque specification, as they are related to vehicle safety during a collision.

N·m (kgf·cm, ft.·lbf) : Specified torque


F30962



CAUTION:
The bolts and nuts must be tightened to the torque specification, as they are related to vehicle safety during a collision.

N·m (kgf·cm, ft.·lbf) : Specified torque

F30963




CAUTION:


The bolts and nuts must be tightened to the torque specification, as they are related to vehicle safety during a collision.

N·m (kgf·cm, ft.·lbf) : Specified torque

F30964


ROOF HEADLINING ASSEMBLY
NO. 2 ROOM LIGHT ASSEMBLY
NO. 1 ROOM LIGHT ASSEMBLY
x 2
MAP LIGHT ASSEMBLY
3RD SEAT ASSIST GRIP ASSEMBLY
ASSIST GRIP COVER
NO. 2 ASSIST GRIP ASSEMBLY RH
ASSIST GRIP ASSEMBLY
3RD SEAT ASSIST GRIP ASSEMBLY
NO. 2 ASSIST GRIP ASSEMBLY LH
ASSIST GRIP ASSEMBLY
SEAT BELT ANCHOR COVER
VISOR ASSEMBLY RH
CENTER VISOR ASSEMBLY RH
CENTER VISOR ASSEMBLY LH
x 2
VISOR BRACKET COVER
VISOR ASSEMBLY LH
VISOR HOLDER
x 2
VISOR BRACKET COVER
INNER REAR VIEW MIRROR STAY HOLDER COVER
VISOR HOLDER
F30965

(e) FRONT SEAT




CAUTION:
The bolts and nuts must be tightened to the torque specification, as they are related to vehicle safety during a collision.

N·m (kgf·cm, ft.·lbf) : Specified torque

F30966


(f) REAR SEAT



CAUTION:
The bolts and nuts must be tightened to the torque specification, as they are related to vehicle safety during a collision.

N·m (kgf·cm, ft.·lbf) : Specified torque

F30967



CAUTION:

The bolts and nuts must be tightened to the torque specification, as they are related to vehicle safety during a collision.

N·m (kgf·cm, ft.·lbf) : Specified torque

F30968