
■ PRECAUTION MULTI-TERRAIN MONITOR SYSTEM

- In the following cases, it may become difficult to see items in the image on the screen, but this does not indicate a malfunction:
  - In the dark (for example, at night)
  - When the temperature near the lens is very high or low
  - When water droplets are present on the television camera, or when humidity is high (for example, when it rains)
  - When foreign matter (for example, mud or salt) is present on the television camera lens
  - When sunlight or headlights are shining directly into the television camera lens
  - When the camera lens is damaged by flying stones
- When washing the vehicle with a high-pressure washer, do not spray water on the rear television camera assembly or surrounding area. High-pressure water can damage the camera.
- If a bright light (for example, sunlight reflected off the vehicle body) is picked up by the camera, the smear effect* (particular to the CCD camera) may occur.



19UBE138I

— REFERENCE —

**: Smear effect*

A phenomenon that occurs when a bright light (for example, sunlight reflected off the vehicle body) is received by the camera and transmitted to the screen. The light source will appear to have a vertical streak above and below it.