TOYOTA PARKING ASSIST-SENSOR SYSTEM


■ DESCRIPTION

- The No. 1 ultra sonic sensor is made more compact, and only one type of sensor that is the same type as the No. 1 ultra sonic sensor is used.
- The screen of the multi-information display has been changed.

■ FUNCTION

1. Multi-information Display

The screen of the multi-information display has been changed as follows:



19UBE127I

▶ Warning Message ◀



Frozen/Dirty



Malfunctioning

19UBE128I