



(IG)
5A
WINCH
2
1
G
B
P
1 B
1 A
1 C
2 A
A42(A), z29(B), z30(C)
Winch Main Relay
(No. 1 Magnet Switch Assembly)
2 Az3
1 Az3
Y
G
B
1 A
2 B
1 B
B
MGSW
IG
E
1 C
z31(A), z32(B), z33(C)
With Magnet Switch
Winch Motor Assembly
B
B
(Diesel)
Battery
Battery
W–B
B
3
A75
Junction
Connector
A5
z1


A 42
Black




A 75
Black




z 29



z 30




z 31



z 32
Gray



z 33



Az3
Gray

