TOYOTA SERVICE BULLETIN

Group: 12 No.: 05 Date: Aug, 13

Landcruiser VDJ76/78/79

Corrections to Repair Manual RM0584E

Please ensure these pages are distributed to all relevant staff for their information; and a copy made available for future reference, with the above repair manual.

Section	Title	Paragraph
INTRODUCTION	REPAIR INSTRUCTION	VEHICLE LIFT AND SUPPORT LOCATIONS (2007/01-2012/08)
		VEHICLE LIFT AND SUPPORT LOCATIONS (2012/08-)

The revised pages listed above are attached.
(The corrected parts are indicated by arrows.)

This Bulletin does not cause the Flat Rate Manual to be changed.

© 2013 Toyota Motor Corporation Australia Limited A.B.N. 64 009 686 097
All rights reserved. This material may not be reproduced or copied, in whole or part, without the written permission of Toyota Motor Corporation Australia Limited, 155 Bertie Street, Port Melbourne, Victoria.


VEHICLE LIFT AND SUPPORT LOCATIONS

(2007/01-2012/08)


IN

w/o Rear Stabilizer:


for Model Code #J71 Series:



for Model Code #J76 Series:



for Model Code #J79 Series:



CAUTION: Do not use the swing arm type lift and plate type lift.

[Added] **Otherwise, the vehicle may fall since its centre of gravity is toward the front of the vehicle.**

H

D223147E02


© 2013 Toyota Motor Corporation Australia Limited A.B.N. 64 009 686 097
All rights reserved. This material may not be reproduced or copied, in whole or part, without the written permission of Toyota Motor Corporation Australia Limited, 155 Bertie Street, Port Melbourne, Victoria.

	JACK POSITION • Front: Under the front differential • Rear: Under the rear differential	**CAUTION:** **When jacking up the vehicle, make sure the vehicle is not carrying any extra weight.**
	SUPPORT POSITION Safety stand	-
	SCREW TYPE JACK POSITION	-


IN

w/ Rear Stabilizer:

for Model Code #J76 Series:



for Model Code #J78 Series, #J79 Series:



CAUTION: Do not use the swing arm type lift and plate type lift.

[Added] **Otherwise, the vehicle may fall since its center of gravity is toward the front of the vehicle.**

0

D223148E02

	JACK POSITION • Front: Under the front differential • Rear: Under the rear differential	**CAUTION:** **When jacking up the vehicle, make sure the vehicle is not carrying any extra weight.**


© 2013 Toyota Motor Corporation Australia Limited A.B.N. 64 009 686 097
All rights reserved. This material may not be reproduced or copied, in whole or part, without the written permission of Toyota Motor Corporation Australia Limited, 155 Bertie Street, Port Melbourne, Victoria.

VEHICLE LIFT AND SUPPORT LOCATIONS


(2012/08-)

w/o Rear Stabilizer:


for Model Code #J71 Series:




for Model Code #J76 Series:



for Model Code #J79 Series, except Double Cab:



for Model Code #J79 Series, Double Cab:



CAUTION: Do not use the swing arm type lift and plate type lift.

[Added] **Otherwise, the vehicle may fall since its center of gravity is toward the front of the vehicle.**

H

D223145E02

© 2013 Toyota Motor Corporation Australia Limited A.B.N. 64 009 686 097
All rights reserved. This material may not be reproduced or copied, in whole or part, without the written permission of Toyota Motor Corporation Australia Limited, 155 Bertie Street, Port Melbourne, Victoria.


IN

	JACK POSITION • Front: Under the front differential • Rear: Under the rear differential	**CAUTION:** **When jacking up the vehicle, make sure the vehicle is not carrying any extra weight.**
	SUPPORT POSITION Safety stand	-
	SCREW TYPE JACK POSITION	-

w/ Rear Stabilizer:


for Model Code #J76 Series:






for Model Code #J78 Series, #J79 Series, except Double Cab:





for Model Code #J79 Series, Double Cab:





CAUTION: Do not use the swing arm type lift and plate type lift.

[Added] **Otherwise, the vehicle may fall since its center of gravity is toward the front of the vehicle.**

0 D223146E02

© 2013 Toyota Motor Corporation Australia Limited A.B.N. 64 009 686 097
All rights reserved. This material may not be reproduced or copied, in whole or part, without the written permission of Toyota Motor Corporation Australia Limited, 155 Bertie Street, Port Melbourne, Victoria.