PP3TT–01

EQUIPMENT

Dial indicator with magnetic base	
Drill	
Feeler gauge	
Micrometer	
Spring tension gauge	
Torque wrench	