F RELAY LOCATIONS

: Center Connector No.2	LHD : Instrument Panel Brace RH (See Page 21)
	RHD : Instrument Panel Brace LH (See Page 21)

