

Power Source
Clock
1
2
3
4
＊1 : w/ Daytime Running Light
＊2 : w/o Daytime Running Light
J6 Junction Connector
P 8 Power Source Control ECU
ACCD
AM1
SSW1
SSW2
Multiplex Communication System (Power Train Control) System<3–9>
Multiplex Communication System (Body Control) System<1–10>
P 2 Panel Relay
T–LP Relay
A15 ACC Relay
7. 5A AM1
7. 5A PANEL
7. 5A ACC
15A DOME
100A DC/DC
25A ACC–B
120A MAIN
F15 Fusible Link Block
Battery
Multiplex Communication System (Body Control) System<1–4>
J25 Junction Connector
J24 Junction Connector
C 9 Clock
ACC
ILL+
B
Cowl Side Panel LH (LHD) Behind the Combination Meter (RHD)
Cowl Side Panel LH
Instrument Panel Brace LH