05IBB–01

PROBLEM SYMPTOMS TABLE

Problem Symptom	Suspected Area	See Page
Only wireless control function is inoperative	1. Transmitter battery 2. Door control transmitter 3. Door control receiver 4. Key slot 5. Wire harness 6. Multiplex network body ECU 7. Instrument panel J/B assy 8. Smart key ECU 9. Wireless door lock buzzer 10. Lighting system	05–1964
No answer–back*1 (hazard warning lamp and wireless door lock buzzer)	1. Wireless door lock buzzer 2. Lighting system 3. Wire harness 4. Multiplex network body ECU	05–1972
No answer–back*2 (hazard warning lamp)	1. Lighting system 2. Wire harness 3. Multiplex network body ECU	05–1976

*1: Australia *2: Except Australia