05IIU–01

PROBLEM SYMPTOMS TABLE

Symptom	Suspected Area	See Page
Key reminder buzzer does not sound.	1. Front door courtesy lamp switch assy (driver side) 2. Combination meter 3. Wire harness 4. Instrument panel J/B assy (Multiplex network body ECU) 5. Key slot 6. Wire harness 7. Transponder key ECU assy	05–2039