
BLOWER ASSY

COMPONENTS

55191–01



P

★ : Use repair screw (parts No.90159–70003) if the screw removed before cannot be tightened.

I38849