
ENGINE IMMOBILISER

SST

	09843-18040	Diagnosis Check Wire No.2	

RECOMMENDED TOOLS

	09082-00040	TOYOTA Electrical Tester	
	(09083-00150)	Test Lead Set	