DTC	63-47	High Temperature

DESCRIPTION

DTC No.	DTC Detection Condition	Trouble Area
63-47	Sensor detects that CD unit temperature is high (Over 80°C).	Radio and navigation assembly

INSPECTION PROCEDURE

HINT:
After the inspection is completed, clear the DTCs.

1	CHECK RADIO AND NAVIGATION ASSEMBLY

(a) Park the vehicle in a cool place.
(b) Check that the temperature of the radio and navigation assembly becomes sufficiently low, then start the engine. Check that the malfunction disappears.
OK:
Malfunction disappears.

NG → **REPLACE RADIO AND NAVIGATION ASSEMBLY**

OK

END

DTC	63-78	DSP Error

DESCRIPTION

DTC No.	DTC Detection Condition	Trouble Area
63-78	An error occurs during the decode process (MP3 / WMA).	-

INSPECTION PROCEDURE

HINT:
After the inspection completed, clear the DTCs.
NOTICE:
- **This code may be output even if there is no malfunction.**
- **If this code is output frequently, replace the radio and navigation assembly.**

1	CLEAR DTC

(a) Clear the DTCs (See page NS-49).
HINT:
These DTCs do not indicate a malfunction.

NEXT

2	RECHECK DTC

(a) Recheck for DTCs and check if the same trouble occurs again.
OK:
Malfunction disappears.

NG → **REPLACE RADIO AND NAVIGATION ASSEMBLY**

OK

END