HORN SYSTEM

PARTS LOCATION



Y

B127542E01

PROBLEM SYMPTOMS TABLE

HORN SYSTEM

Symptom	Suspected area	See page
Horn does not sound	1. Horn button switch	-
	2. High pitched horn assembly	HO-7
	3. Low pitched horn assembly	HO-5
	4. Horn relay assembly	HO-3
	5. Wire harness	-