


(Cont. next page)



(Cont. next page)

Electronically Controlled Transmission and A/T Indicator




Electronically Controlled Transmission and A/T Indicator
9
10
11
12
W–L
B–R
R
J18 Junction Connector
J19 Junction Connector
J47 Junction Connector
P 1 Park/Neutral Position SW
C10 Combination Meter
IG+
P
R
N
D
4
3
2
L
Speedometer
MICRO COMPUTER
DRIVE IC
POWER SUPPLY CIRCUIT
BEAN IC
Multiplex Communication System(BEAN)<1–9><1–10>
Instrument Panel Brace LH
IF
L–Y
Y–R
L–W
R–B
Y–G
G
BR