
# PRECAUTION


## GENERAL REPAIR INSTRUCTIONS

### 1. WORK PRECAUTIONS





(a) VEHICLE PROTECTION

(1) When welding, protect the painted surfaces, windows, seats and carpet with heat resistant, fireproof covers.





(b) SAFETY

(1) Never stand in a direct line with the chain when using a puller on the body or frame, and be sure to attach a safety cable.




(2) Before performing repair work, check for fuel leaks. If a leak is found, be sure to close the opening completely.

(3) If it is necessary to use a flame in the area of the fuel tank, first remove the tank and plug the fuel line.




(c) SAFETY WORK CLOTHES

(1) In addition to the usual mechanic's wear, cap and safety shoes, the appropriate gloves, head protector, glasses, ear plugs, face protector, dust-prevention mask, etc. should be worn as the situation demands.

| Code | Name |
|---|---|
| A | Dust-Prevention Mask |
| B | Face Protector |
| C | Eye Protector |
| D | Safety Shoes |
| E | Welder's Glasses |
| F | Ear Plugs |
| G | Head Protector |
| H | Welder's Gloves |