
■PRECAUTION FOR REAR VIEW MONITOR SYSTEM OPERATION

- In the following cases, it may become difficult to see items in the image on the screen, but this does not indicate a malfunction.
  - In the dark (for example, at night)
  - When the temperature near the lens is very high or low
  - When water droplets are present on the television camera, or when humidity is high. (for example, when it rains)
  - When foreign matter (for example, mud or salt) is present on the television camera lens
  - When the sun or the beam of headlights shines directly into the television camera lens
- If a bright light (for example, sunlight reflected off the body of a vehicle) is picked up by the television camera, the smear effect*, a phenomenon experienced by a CCD camera, may occur.



241BE68

Smear Effect

— REFERENCE —

**: Smear effect*
A phenomenon that occurs when a bright light is received by the television camera; and transmitted to the screen, the light source will appear to have a vertical streak above and below it.