
■ INTERIOR LIGHT

The position of the front footwell light for the driver seat has been changed from right side to left side.



24WBE005O