



For JBS Units without On-board Door Lock Relays:

**Requires
(1) 778 or
(2) 775's**



For JBS Units with On-board Door Lock Relays:



KE-100, KE-150 and 1702

