

## DIAGNOSTIC TROUBLE CODE CHART

DTC No. (See Page)	Detection Item	Trouble Area
B2795 (DI-513)	Unmatched key code	<ul style="list-style-type: none"> <li>• Key</li> <li>• Unregistered key inserted before</li> </ul>
B2796 (DI-514)	No communication in immobiliser system	<ul style="list-style-type: none"> <li>• Key</li> <li>• Transponder key coil</li> <li>• Amplifier</li> <li>• Wire harness</li> <li>• Engine &amp; ECT ECU</li> </ul>
B2797 (DI-518)	Communication malfunction No.1	<ul style="list-style-type: none"> <li>• Communication contents</li> <li>• Unregistered key inserted before</li> </ul>
B2798 (DI-524)	Communication malfunction No.2	<ul style="list-style-type: none"> <li>• Key</li> <li>• Transponder key coil</li> <li>• Amplifier</li> <li>• Wire harness</li> <li>• Engine &amp; ECT ECU</li> </ul>

### HINT:

To reduce the unnecessary exchange of Engine & ECT ECU, check that a trouble occurs with the original Engine & ECT ECU at the time of exchanging Engine & ECT ECU and the trouble will disappear with a new Engine & ECT ECU.