


INSTALLATION

1. INSTALL COMBINATION METER ASSEMBLY

- (a) Connect the connectors.
- (b) Install the combination meter assembly with the 4 screws.



2. INSTALL INSTRUMENT CLUSTER FINISH PANEL SUB-ASSEMBLY

- (a) Engage the 4 clips and install the instrument cluster finish panel sub-assembly.

3. CONNECT CABLE TO NEGATIVE BATTERY TERMINAL

4. PERFORM INITIALIZATION

NOTICE:

Some systems need initialization when disconnecting the cable from the negative battery terminal.

