

# insider info.

## **DTC P0507 - Idle Control System RPM Higher Than Expected**

If you find yourself diagnosing a DTC P0507 — Idle Control System RPM higher than expected — check to see if the accelerator or cruise control cables are adjusted properly.

