



insider info

Forester Rear Gate Service

If you are servicing a Forester and find the rear upper gate door plug not installed properly, the problem may be that the hole size is slightly too big for the plug. SOA suggests you put a small amount of silicone sealer on the plug and re-install the plug into the hole.