

SERVICE BULLETIN

APPLICABILITY ALL SUBARU MODELS
SUBJECT: DOOR FABRIC PEELING OFF

DATE 02

If you receive a customer complaint of the fabric trim peeling away from the door panel, do not replace the door panel. Follow the instructions below to repair the door panel.

NOTE: DO NOT REMOVE THE DOOR PANEL FROM THE VEHICLE.

MATERIALS NEEDED

Disposable latex gloves or equivalent.
Cyanoacrylate glue, examples: 3M Part No. 051135-08155 "Quick Fix Adhesive".

NOTE: THE GLUE MUST BE ABLE TO BOND PLASTIC TO PLASTIC FIBER.

1. Carefully pull back the fabric trim only in the area peeling away. Do not remove the whole trim piece.
2. Apply the glue to the back of the fabric trim.
3. Apply pressure to hold the fabric trim in place for a minimum of five minutes.

This procedure can be claimed for vehicles within the terms of the Subaru Limited Warranty and using the following:

ITEM DESCRIPTION/ FAILURE CODE	OPERATION NUMBER	LABOR DESCRIPTIONS	TIME
DOOR TRIM PANEL YHG-48	A191-231	DOOR TRIM PANEL - REPAIR	0.2 HRS.

CAUTION

VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicle or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

*Trademarks