

SERVICE BULLETIN

APPLICABILITY

1992 LEGACY

DATE

12-16-92

SUBJECT:**SERVICE MANUAL CORRECTIONS**

The page reference numbers used with the "Troubleshooting Chart with Select Monitor" are incorrect. Please correct Section 2-7 starting with page reference number [T900] using the chart below.

<u>MODE</u>	<u>OLD NUMBER</u>	<u>NEW NUMBER</u>
F02	T7K0	T8K0
F04	T7C0	T8C0
F06	T7E0	T8E0
F07	T7I0	T8I0
	T7F0	T8F0
	T7N0	T8N0
F09	T7C0	T8C0
	T7A0	T8A0
F10	T7I0	T8I0
F11	T7M0	T8N0
F12	T7M0	T8N0
	T7P0	T8Q0
	T7R0	T8S0
F13	T7J0	T8J0
F14	T7J0	T8J0
F15	T7J0	T8J0
F17	T7F0	T8F0
F19	T7T0	T8P0
F20	T7T0	T8P0

CAUTION

VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.