

18-11-92

SUBARU.

SERVICE BULLETIN

APPLICABILITY

1992 LEGACY

DATE

12-16-92

SUBJECT:

SERVICE MANUAL CORRECTIONS

The FWD and AWD terminal designations found on page 4-4, page reference number [T6C0], Fig. 160 are incorrect.

Please make correction to read FWD terminal 5, AWD terminal 22.

CAUTION