

## SERVICE BULLETIN

**APPLICABILITY**

ALL NON-TURBO LEGACY VEHICLES

**DATE**


07-06-93

**SUBJECT:**

LEGACY FUEL INJECTION CODE 49

If you should encounter a Non-Turbo Legacy which indicates a Code 49 (Air Flow Sensor), use the trouble tree below to diagnose the vehicle.

(Be sure to make a note in the affected Service Manuals to refer to this bulletin.)

**CAUTION**

VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition. Impreza is a Trademark and Legacy, Justy, Loyale and Subaru SVX are Registered Trademarks.