

SERVICE BULLETIN

APPLICABILITY

ALL LEGACY AND IMPREZA VEHICLES
EQUIPPED WITH 4EAT

DATE

05-16-

SUBJECT:**INSTALLATION OF THE SPEEDOMETER CABLE ADAPTER**

Should it become necessary to remove and install the speedometer cable adapter from the transmission, make sure the rubber gasket and the metal flat washer beneath the adapter are also removed. These parts normally will stay attached to the adapter but sometimes may break loose and stay in the case. If you fail to remove them and you are installing a new transmission in the vehicle, these missing parts may cause the speedo gear shaft to bind, possibly resulting in stripped speedo drive gears. However, if you are replacing just the adapter, be certain that the old rubber gasket and flat washer are removed since the new adapter comes with these parts attached. If the new adapter is installed on top of the old parts, it may not engage the shaft properly.

When tightening the adapter, caution should be taken not to overtighten it.

The following procedure is recommended when installing the unit.

1. Hand tighten the cable adapter until it bottoms out.
2. Using a wrench, tighten the adapter by rotating it clockwise 45 to 90 Degrees. No additional tightening is required.

CAUTION

VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition. Impreza is a Trademark and Legacy, Justy, Loyale and Subaru SVX are Registered Trademarks.